

## MegaSquirt Installation Wiring Diagram Super420A Wasted Spark

Color code corresponds with RS Autosport wiring harness kit  
Adapted from diagram by Lance Gardiner, <http://www.megasquirt.info>

### Auxiliary Wire List

- 3, SPR1 - Shift Light Output
- 4, SPR2 - Fan Relay Control Output
- 5, SPR3 - Boost Control Solenoid Output
- 6, SPR4 - Tachometer Signal Output
- 25, S1 - KnockSenseMS or Table Switching Input
- 27, S2 - EGT Sender Input
- 29, S3 - Launch Control Input
- 31, S4 - Ignition Output B (Cyl. 2 and 3)
- 36, S5 - Ignition Output A (Cyl. 1 and 4)

